

---

---

**Safety Bulletin**  
**PROsine™ 1000/1800**  
**Inverters (Hard-wire**  
**versions)****Shock Hazard Due to**  
**Missing Neutral-to-Ground**  
**Bonding Wire**

---

---

## Overview

The 120 Vac output PROsine 1000 and PROsine 1800 inverters are designed with the output neutral connected to ground, as required by Canadian and U.S. electrical codes and standards. Xantrex has discovered a manufacturing error in certain models that resulted in this Neutral-to-Ground (N-G) “bonding wire” being omitted. As a result, the neutral voltage may rise above ground, creating a shock hazard, even though the unit appears to be functioning normally.

Xantrex has corrected the manufacturing error and removed as many of the faulty products as possible from the distribution chain. However, some of the affected products have reached customers and are in service. Xantrex is providing easy-to-install repair kits to customers so they may fix the defect themselves. Alternatively, Xantrex will repair the PROsine inverters for those customers who do not want to install the kit.

In the meantime, this Safety Bulletin explains the problem, outlines the conditions that create a hazard, states what precautions to take, and lists the serial numbers of affected inverters.

## Applicability

This bulletin applies only to PROsine 1000 and PROsine 1800 inverters with 120 Vac output, 12 Vdc or 24 Vdc input, and with the “hard-wire” output style option, manufactured between May and September, 2001. The part numbers and serial numbers of the affected units are listed in Appendix A. This bulletin does not apply if your PROsine inverter has the GFCI receptacle output option or the hard-wire with built-in transfer relay output option.

## Explanation

The 120 Vac output PROsine 1000 and PROsine 1800 inverters are designed with the output neutral bonded to (connected to) ground, as required by Canadian and U.S. electrical codes and standards. The purpose of this N-G bonding is to ensure there is no voltage on the output neutral with respect to ground. This maintains the expected normal state of a 120 Vac system—the line conductor is at 120 Vac above ground and the neutral conductor is at (or close to) zero volts above ground. As a result of the missing N-G bonding, the neutral voltage may rise above ground, typically by approximately 60 Vac, creating a shock hazard on circuits and loads connected to the inverter. Other than this neutral-to-ground voltage, the inverter operates normally, so this hazard could go unnoticed.

The hazard is reduced, but not eliminated, by the inaccessibility of bare, live parts connected to the neutral (and line) circuits in most typical AC-powered equipment. Two notable exceptions are the outer screw-shell on standard household lamps and old-style “plug” fuses. In both cases the neutral-connected screw-shell is partially accessible with the lamp or fuse in place, and is completely accessible with the lamp or fuse removed.

Since there is a shock hazard involved, the safest course of action is to stop using the faulty unit and disconnect power from it until the problem is fixed. Xantrex has produced a field-installable N-G bonding kit for those customers who wish to fix the unit themselves. We will repair faulty PROsine inverters for those customers who prefer not to install the bonding kit themselves.

## **What to do if your PROsine inverter is affected**

If your PROsine inverter has one of the serial numbers listed in Appendix A, stop using the product. Disable the inverter by turning off the front panel switch and disconnecting the battery from the DC input. Then contact Xantrex Customer Service to determine how to receive the field-installable N-G bonding kit or to have your unit repaired.

## **Contact Information**

If you determine that your PROsine 1000 or PROsine 1800 inverter is one of the affected ones, please contact Customer Service in one of the following ways:

Phone: 1-800-670-0707, press “1”

Fax: 1-800-994-7828

Email: [support.prosine@xantrex.com](mailto:support.prosine@xantrex.com)

Web: [www.xantrex.com](http://www.xantrex.com)

---

---

## **Appendix A**

### **Part Numbers and Serial Numbers of Affected Units**

---

---

| <b>Unit</b>               | <b>Serial Numbers</b> |
|---------------------------|-----------------------|
| PROsine 1000/12 hard-wire | 21307801 to 21307810  |
| Part number 806-1001      | 21336673 to 21336699  |
|                           | 21336700 to 21336734  |
|                           | 21336735 to 21336772  |
|                           | 21336887 to 21336899  |
|                           | 21336900 to 21336906  |
|                           | 21352221 to 21352260  |
|                           | 21435575 to 21435576  |
|                           | 21435578              |
|                           | 21435581 to 21435600  |
|                           | 21435601 to 21435614  |
|                           | 21524051 to 21524052  |
|                           | 21524057 to 21524060  |
|                           | 21524063 to 21524066  |
|                           | 21524071 to 21524072  |
|                           | 21524075 to 21524076  |
|                           | 21524081 to 21524084  |
|                           | 21524087 to 21524090  |
|                           | 21524097 to 21524114  |
|                           | 21524217 to 21524218  |

| <b>Unit</b>                                       | <b>Serial Numbers</b>  |
|---|--|
| PROsine 1800/12 hard-wire<br>Part number 806-1801 | 21258061 to 21258062<br>21258068<br>21258073 to 21258080<br>21258153 to 21258162<br>21258172 to 21258175<br>21269780 to 21269797<br>21269800 to 21269801<br>21269805 to 21269809<br>21269831 to 21269832<br>21269835 to 21269836<br>21269841 to 21269842<br>21281207 to 21281229<br>21281231 to 21281265<br>21281267 to 21281280<br>21295581 to 21295587<br>21336623 to 21336626<br>21336649 to 21336652<br>21336655 to 21336656<br>21485001 to 21485020<br>21485039 to 21524540 |
| PROsine 1800/24 hard-wire<br>Part number 806-1851 | 21270097 to 21270114<br>21515061 to 21515110<br>21525324 to 21525325<br>21525334 to 21525337<br>21525340<br>21525343<br>21525422 to 21525433   |

| Unit  | Serial Numbers       |
|---|----------------------|
| PROsine 1800/24 hard-wire<br>Part number 806-1860 | 21270146             |
|   | 21270148             |
|   | 21435226             |
|   | 21435232             |
|   | 21435236             |
|   | 21435242             |
|   | 21435244             |
|   | 21435723 to 21435724 |
|   | 21435726             |
|   | 21435731             |
|   | 21435733 to 21435734 |
|   | 21535685 to 21535686 |
|   | 21535688             |
| PROsine 1800/24 hard-wire<br>Part number 806-1051 | 21281297 to 21281302 |

PROsine is a trademark and Statpower is a registered trademark of Xantrex International. Xantrex is a registered trademark of Xantrex International.

© 2001 Xantrex International. All rights reserved.

Safety Bulletin: *PROsine™ 1000/1800 Inverters (Hard-wire versions) - Missing Neutral-to-Ground Bond Wire Create a Shock Hazard* © November 2001 Xantrex International

UNLESS SPECIFICALLY AGREED TO IN WRITING, XANTREX TECHNOLOGY INC. ("XANTREX")

(a) MAKES NO WARRANTY AS TO THE ACCURACY, SUFFICIENCY OR SUITABILITY OF ANY TECHNICAL OR OTHER INFORMATION PROVIDED IN ITS MANUALS OR OTHER DOCUMENTATION.

(b) ASSUMES NO RESPONSIBILITY OR LIABILITY FOR LOSS OR DAMAGE, WHETHER DIRECT, INDIRECT, CONSEQUENTIAL OR INCIDENTAL, WHICH MIGHT ARISE OUT OF THE USE OF SUCH INFORMATION. THE USE OF ANY SUCH INFORMATION WILL BE ENTIRELY AT THE USER'S RISK.

Part number: 512-0023-01-01